Maryland Historical Trust

Maryland Inventory of Historic Properties Number:									
MARYLAND HISTORICAL TRUST									
Eligibility RecommendedX			Eligibil	-					
Criteria:ABC	D Considerations: _	A _	B	_c	_D	_E _	_F _	_G _	_None
Comments:									
Reviewer, OPS:Anne E. Bruder				Date	3 A	April 2	2001_		_
Reviewer, NR Program: Peter E. Kur	tze			Date	:3	April	2001		

Maryland Inventory of Historic Properties Historic Bridge Inventory Maryland State Highway Administration Maryland Historical Trust

Maryland Historical Trust
SHA Bridge No. 10065 Name: MD 140 over the Monocacy River
<u>Location:</u> Street/Road Name and Number: <u>MD 140 (Taneytown Pike)</u>
City/Town: Bridgeport Vicinity X
County: Frederick
Ownership: X State_County_Municipal_Other
This bridge projects over:RoadRailway_X_WaterLand
Is the bridge located within a designated district: _yes X_no
_NR listed district_NR determined eligible district _locally designated_other Name of District
Bridge Type:
Timber BridgeBeam BridgeTruss-CoveredTrestleTimber-and-Concrete
_Stone Arch
_Metal Truss
_Movable Bridge _Swing _Bascule Single Leaf_Bascule Multiple Leaf _Vertical Lift_Retractile_Pontoon
Metal GirderRolled Girder Concrete EncasedPlate GirderPlate Girder Concrete Encased
_Metal Suspension
Metal Arch
_Metal Cantilever
X Concrete Arch Concrete Slab Concrete Beam Rigid Frame
_Other Type Name

Describe Setting:

Bridge 10065 carries MD 140 over Monocacy River in Frederick County. MD 140 runs east-west over the southern flowing Monocacy River. The area immediately adjacent to the bridge has light residential development.

Describe Superstructure and Substructure:

Bridge 10065 is a triple-span filled concrete arch. The length of the bridge is 168 feet. The first and third spans have clear spans of 50 feet while the middle span has a clear span of 56 feet. The rise is approximately 14 feet high from springline to crown. The spandrel walls are approximately 13 feet high and 8 feet from the top of the pier to the crown. The abutments are approximately 13 feet high and 24 feet wide. The 2 identical piers are 4 feet 10 inches wide with a 6-foot nose cone. There is a clear roadway width of 24 feet, with an overall width of 27 feet 2 inches. According to a 1996 inspection report, the bridge is in satisfactory condition with a sufficiency rating of 76.2.

The parapets are original. The builders used a closed parapet design. This reinforced concrete railing consists of vertical posts securely fastened by dowels to the structure, horizontal rails, and solid panels that fill the space between posts and the railings. The panels may be precast, and the posts and rails were built in place. Expansion joints separate the panels.

Discuss Major Alterations:

There have been no major alterations to this bridge. In 1980 tie bolts and scuppers were added to the bridge.

When Built: 1925

Why Built: Replacement of dangerous one-lane bridges.

Who Built: State Roads Commission
Who Designed: State Roads Commission

Why Altered: N/A

Was this bridge built as part of an organized bridge building campaign? No, this bridge was not built as part of an organized bridge building campaign.

Surveyor Analysis:

This bridge may have NR significance for association with:

XA Events __Person XC Engineering/Architectural

This bridge was determined eligible by the Interagency Review Committee in February 1996.

Was this bridge constructed in response to significant events in Maryland or local history?

Between 1924 and 1926 the state was confined to completing the gaps in important arteries out of Frederick County. The dangerous one-way bridges on the main highways in the county were rapidly being replaced with new structures. In 1925 a single lane covered bridge was replaced by Bridge 10065 and the old road was relocated upstream by approximately one-quarter of a mile.

Is the bridge located in an area that may be eligible for historic designation and would the bridge add to or detract from historic and visual character of the possible district?

This bridge is not located in an area that is eligible for historic designation.

F-6-119

Is the bridge a significant example of its type?

Yes this bridge is a significant example of the State Roads Commission's efforts from 1910 until 1945 to eliminate dangerous geometric alignments. The development of standardized plans helped to facilitate this process of standardizing lane widths and alignments.

Does the bridge retain integrity of the important elements described in the Context Addendum?

Yes this bridge retains integrity of its character defining elements. Although some repairs were made to the wingwalls, the spandrel walls, the parapets, and the abutments, all are original and have only moderate deterioration.

Should this bridge be given further study before significance analysis is made?


No this bridge should not be given further study.			
Bibliography: County inspection/bridge files	SHA inspection/bridge files	X	
Other (list):	. 0 =		

Surveyor:

Name: Stacie Y. Webb Date: February 1996

Organization: State Highway Admin. Telephone: (410) 545-8559

Address: 707 N. Calvert Street, Baltimore, Maryland Edited by P.A.C. Spero & Company, December 1997.





•
Name 10065- MD140 OVER MONDEAU RIVER
County/State FRE DERICK COUNTY/MD
Name of Photographer FRANK JULIANO
Date 2/05
1

Description APPROACH EAST

Inventory # <u>F-6-119</u>

Location of Negative SHA



		- 1 110
Inventory	#	F-6-119

Name 10005-MO14D OVER MONICACY RIVER County/State FREDERICK COUNTY IMP Name of Photographer FRANK JULIANS Date 2195

Location of Negative SHA Description ELEVATION LADIGING NORTH



111.012225				
Name 10065-	MOIHO	OVERIL	ONDCACY	RIVER
County/State	FICELL	- KIUK	K TIMI	200
Name of Photo	ographer	FYORT	10 30101	

Description APPROACH WEST

Inventory # F-6-119

Location of Negative ____SAA__



Name 10005-MD140 OVER MONUCACY RIVER County/State FREDERICC COMMTY /MD Name of Photographer FRANK JULIANO Date _ 795

Description EVE VATION LODKING SOUTH

Location of Negative SHA

Inventory # _ *F-6-119*